

Project 3 area photos.



Project 3 area. Ditch line repairs required.



Project 3 area – Sediment removed and area hydro seeded, wattle inlet protection installed.

Project 5 area photos.



Slope repair required. Slope too steep to establish permanent vegetative groundcover, rolled erosion control product incorrectly installed.



Eamon Drive grading and shaping on going. – Slopes hydro seeded.

Project 2 area – Restoration work performed by Dalziel Enterprises.



Slope repair. Rolled erosion control product installed on slope, ditch line shaped and excelsior matting installed on road shoulder. Project 2 area by Dalziel Enterprises.



Drop Inlet area repair and restoration. Project 2 area by Dalziel Enterprises.